

**FIRE INSPECTOR'S
INTER-OFFICE CORRESPONDENCE**

TO: Genaro Argenio, Planning Board Chairman

FROM: Kenneth Schermerhorn, Asst. Fire Inspector

SUBJECT: PB-08-19
1011 Rte. 94
SBL: 69-4-26.13

DATE: December 8, 2008

Fire Prevention Reference Number: FPS-08-051

A review of the above referenced site plan has been conducted and is disapproved for the following reasons:

- 1) Building size requires a sprinkler system.
- 2) A hydrant must be installed on property in the vicinity of sprinkler siamese & location shown on site plan.